

How to use $L(\mu, \sigma)$?

I might make "maximum likelihood" (point) estimates of μ, σ by finding $(\hat{\mu}, \hat{\sigma})$ that maximizes $L(\cdot, \cdot)$.


1. When the sample range of $x_1^*, x_2^*, \dots, x_n^*$ is at least 2, $L(\mu, \sigma)$ is nice — it's mound-shaped and smooth and any sensible method will work to find maximizers $(\hat{\mu}, \hat{\sigma})$.

(You can do this easily with Karen Jensen's CONEST program; see Professor Vardeman's Stat 531 Web page.)

2. When the sample range of x_1^*, \dots, x_n^* is 1 then all (μ, σ) pairs with σ small and

$$\Phi\left(\frac{\min x_i^* + .5 - \mu}{\sigma}\right) \approx \frac{\#[x_i^* = \min x_i^*]}{n}$$

have nearly the same (and nearly "maximum") likelihood ($L(\mu, \sigma)$).



Here I will guess that σ is small and μ and σ are such that the normal (μ, σ^2) probability to the left of $\min x_i^* + .5$ is

$\frac{\# [x_i^* = \min x_i^*]}{n}$. Let $m = \# [x_i^* = \min x_i^*]$. Then


$$= \text{"max"} L(\mu, \sigma) = \sup L(\mu, \sigma) = \left(\frac{m}{n}\right)^m \cdot \left(1 - \frac{m}{n}\right)^{n-m}$$

3. When the sample range of $x_1^*, x_2^*, \dots, x_n^*$ is 0 all (μ, σ) pairs with σ small and

$$x_i^* - .5 < \mu < x_i^* + .5$$

have nearly the same (and nearly "maximum")

$L(\mu, \sigma)$.



Here I guess that σ is small and μ is within .5 of common x_i^*

$$\text{"max"} L(\mu, \sigma) = \sup L(\mu, \sigma) = 1.$$

It is also possible to use $L(\mu, \sigma)$ to guide making of confidence sets for (μ, σ) , or μ , or σ .

Confidence Sets for (μ, σ) :

Confidence Set = $\{(\mu, \sigma) \mid L(\mu, \sigma) \text{ is not too much smaller than "max" } L(\mu, \sigma)\}$

Large sample theory \Rightarrow $(1-\alpha)$ confidence

set for $(\mu, \sigma) = \{(\mu, \sigma) \mid \mathcal{L}(\mu, \sigma) > \sup_{\mu, \sigma} \mathcal{L}(\mu, \sigma)$

where $\left. \begin{array}{l} -\frac{1}{2} \chi_2^2 \end{array} \right\}$

$$\mathcal{L}(\mu, \sigma) = \ln L(\mu, \sigma)$$

and $\chi_2^2 =$ upper α point of χ_2^2 dsrn.

Confidence Intervals for μ :

Let $L^*(\mu) = \sup_{\sigma} L(\mu, \sigma)$ "profile likelihood" for μ


Using the "most likely" value of σ for a given μ , this in some sense measures how likely μ is.

As it turns out there are 3 basic shapes for $L^*(\mu)$ depending upon


range of χ_1^* , χ_2^* , \dots , χ_n^* .

Let $\mathcal{L}^*(\mu) = \ln L^*(\mu)$.

Range=0:



Range=1:



Case where there are more observations at $\min x_i^*$ than at $\max x_i^*$.

This doesn't work too well for small n .

- Happily Johnson Lee has found replacements for χ^2 that work fine for any n — $c(n, \alpha)$:

$$c(n, \alpha) = n \cdot \ln \left(\frac{t_{\alpha/2: (n-1)}^2}{n-1} + 1 \right)$$

(See page 16 of the Notes)


- $t_{\alpha/2: (n-1)}$: upper $\alpha/2$ point of t_{n-1} .

Confidence Sets for σ :


$$\text{Let } L^{**}(\sigma) = \sup_{\mu} L(\mu, \sigma)$$

("profile likelihood for σ ")

Range = 0 or 1: Let $\mathcal{L}^{**}(\sigma) = \ln L^{**}(\sigma)$



Range ≥ 2 :



As a way of making CI's for σ

I'll use

Confidence interval for $\sigma = \left\{ \sigma \mid \begin{array}{l} L^{**}(\sigma) \text{ is not too much} \\ \text{below maximum possible} \end{array} \right\}$

Large sample theory says that

approximately

$(1-\alpha)$ level CI for $\sigma = \left\{ \sigma \mid \mathcal{L}^{**}(\sigma) > \sup_{\sigma} \mathcal{L}^{**}(\sigma) - \frac{1}{2} \chi_1^2 \right\}$


This turns out to work poorly for small n — Johnson Lee has found replacements for χ_1^2 so that the resulting intervals hold nominal confidence level (see §1.7 of the Notes for details).

Start Process Monitoring

Read V&J: 3.1-3.5, 4.3, 4.4

"Shewhart" "Control Charting"

Basic Problem: Process "watching" for purposes of change detection and elimination.



Watch for "lack of physical stability"

Implication: When such is detected some (unspecified) physical intervention is needed (to set things "aright")

"process stability" = ?

Complete lack of variation is too much to hope for.

Classical/Shewhart interpretation:

"process stability" = pattern of variation
(over time) is "constant"
in the sense that
measurements generated
"look iid"

Possibly a better/more enlightened/
modern interpretation:

"process stability" = pattern of observed
variation is "constant"
in the sense that data
look like they come
from a fixed stochastic
model (one that
we "expect")

Process monitoring is about
change detection.

Original Shewhart "Control Charting" Idea

- 1) Identify some sensible measure of process performance/behavior to plot against time (Q)
- 2) Apply some probability theory to identify a sensible "stable process" distribution for Q .
- 3) Establish upper and lower "control limits" based on 2).

These limits are meant to separate "typical" values of Q from ones that are "rare" if indeed the process is "stable".


— You might get them by

a) Using small lower and upper % points of the dsn in 2)

or (nearly equivalently)

b) $\mu_Q - 3\sigma_Q = LCL_Q$
 $\mu_Q + 3\sigma_Q = UCL_Q$ } "3 sigma limits"

4) Plot values of Q against time and declare the process "out of control" (and thus in need of physical intervention) at any period where Q falls outside limits from 3).



Various particular Q lead to different famous charts:

\bar{x} , R , s , $\hat{\sigma}$, p , np , c , u , etc.

See 3.2 and 3.3 of V&J — Table 3.11 of V&J for a summary of these \uparrow standard charts. (page 107)

Additional Introductory Qualitative Points:

① Concerning situations where measurements y are processed into a Q

Control limits on Q	\neq	Engineering Specifications on y
↑		↑
have to do with assessing process stability (<u>applied to Q</u>)		have to do with defining functionality/ acceptability of <u>individuals</u>

② Standards Given vs. Retrospective Contexts / Analyses

"Standards given" context:

- Before beginning process monitoring one is furnished with sensible values for process parameters and these are used to create control limits that are applied to Q 's as they are generated.
- e.g., if "standard values" for μ and σ are $\mu=5.0$ and $\sigma=1.715$ and I'm going to do Shewhart \bar{x} charting...

Control limits for \bar{x} (based on $n=5$):

$$\begin{aligned}UCL_{\bar{x}} &= \mu_{\bar{x}} + 3\sigma_{\bar{x}} \\ &= 5 + 3 \cdot \frac{1.715}{\sqrt{5}} = 7.3\end{aligned}$$

$$\begin{aligned}LCL_{\bar{x}} &= \mu_{\bar{x}} - 3\sigma_{\bar{x}} \\ &= 5 - 3 \cdot \frac{1.715}{\sqrt{5}} = 2.7\end{aligned}$$

"Retrospective" / "as past data" context:

Here one is furnished with a data record (from, say, r periods) and is asked:

"Does stability over the period of data collection seem plausible?"

Here the only obvious method of operation is:

- a) temporarily assume stability over the period of study and make provisional estimates of (supposedly constant) parameters.
- b) use the estimates from a) to make control limits, apply those retrospectively to the data in hand to criticize the stability assumption.

Jargon for types of process monitoring data:

"Attributes Data" Scenarios (Count Data)

1. % (fraction) nonconforming (defective) context:


o o o | o x o o x d o o
sample of n widgets

items are individually
either conforming
or nonconforming

$X = \#$ nonconforming in sample np charting

$\frac{X}{n} = \hat{p} =$ fraction nonconforming P charting

2. mean nonconformities (defects)
per unit context:



k (possibly noninteger) inspection units

Each inspection unit may have multiple
nonconformities/defects -

$X =$ total nonconformities

$k=1$ plot X c charting u charting

plot $\frac{X}{k} = \hat{u} =$ nonconformities/unit

"Variables Data" Scenarios (Measurements)

x_1, x_2, \dots, x_n : measurements on a sample of n items

Charts for distributional spread / "process short term variation"

R, s

Charts for process aim/location:

$\bar{x} (\tilde{x})$

Usual control limits for these come from normal distribution theory.

Example $n=5$ \bar{x}, R

Standards Given ($\mu=5, \sigma=1.715$)

\bar{x} chart limits:

$$UCL_{\bar{x}} = \mu_{\bar{x}} + 3\sigma_{\bar{x}} = 5 + 3 \cdot \frac{1.715}{\sqrt{5}}$$

$$LCL_{\bar{x}} = \mu_{\bar{x}} - 3\sigma_{\bar{x}} = 5 - 3 \cdot \frac{1.715}{\sqrt{5}}$$

R chart limits:

$\mu_R \leftarrow$ "center line" for R chart

$$\begin{aligned} \text{center line} &= d_2(5) \cdot \sigma = 2.326 (1.715) \\ &= 3.99 \end{aligned}$$

$$\begin{aligned} UCL_R &= \mu_R + 3\sigma_R = d_2(5) \cdot \sigma + 3 \cdot d_3(5) \cdot \sigma \\ &= \sigma \underbrace{(d_2(5) + 3d_3(5))}_{D_2(5)} \end{aligned}$$

$$\begin{aligned} LCLR & \\ = \mu_R - 3\sigma_R & \\ = D_1(n) \cdot \sigma &= 1.715 (4.918) \\ = 0 &= 8.43. \end{aligned}$$

$d_2(n)$, $d_3(n)$, $D_2(n)$, etc.: see Table A.1 on page 509 of V&J (the text).