

# CUSUM Charts

(Section 4.2 of Vardeman and Jobe)



# Basic Motivation

- It may be difficult to see small changes in the distribution of a plotted statistic  $Q$  on a Shewhart chart
- It can be easier to see those changes if one “accumulates” deviations from some standard value for  $Q$
- A “raw” Cumulative Sum sequence is defined by

$$CUSUM_i = (Q_i - k) + CUSUM_{i-1}$$


# Example

- $Q_s$  Normal with mean .5 and std dev 1.0
- $CUSUM_s$  of  $Q_s$  with  $CUSUM_0 = 0$  and  $k = 0$




# Interpreting a CUSUM

- It is the *slope* on a CUSUM plot that indicates how average  $Q$  differs from  $k$
- Example 4.2 ( $k=25$ )



# How to Use This in SPM?

- One possibility (I believe, essentially never used in real practice!) is to apply an appropriate “V-mask”



# One-Sided “Decision Interval” CUSUMs

- “High Side” CUSUM

$$U_i = \max \left[ 0, (Q_i - k_1) + U_{i-1} \right]$$


- “Low Side” CUSUM

$$L_i = \min \left[ 0, (Q_i - k_2) + L_{i-1} \right]$$

- All of  $k_1$  and/or  $k_2$ ,  $U_0$  and/or  $L_0$  are (appropriately chosen) parameters of the scheme

# More Decision Interval CUSUMs

- Raw CUSUMs with a “restart” feature
- “Reference values”  $k_1$  and  $k_2$  are typically chosen above and below an ideal  $Q$
- “Out-of-control” signals derive from decision levels  $h$  and  $-h$



# Choice of Scheme Parameters

- Common choice of starting values is

$$U_0 = 0 \text{ and/or } L_0 = 0$$

- For a given choice of  $k_1$  and/or  $k_2$  and a normal “all-OK” distribution for  $Q$ , Tables 4.5 and 4.6 can be used to pick  $h$  providing a desired mean time between false-alarms (a desired “all-OK ARL”)

- To enter the tables one must standardize by

$$K = \frac{k_1 - \mathbf{m}_Q}{\mathbf{s}_Q} \quad \text{or} \quad K = \frac{\mathbf{m}_Q - k_2}{\mathbf{s}_Q}$$

and read out  $H$



# More Choice of Parameters

- Then set  $h = H\mathbf{s}_Q$
- For simultaneous high and low side schemes with

$$\frac{k_1 + k_2}{2} = \mathbf{m}_Q$$

and *all-OK*  $ARL=370$ , Table 4.6 shows appropriate choice of  $H$  to be

$K$					
.25	.50	.75	1.00	1.25	1.50
8.01	4.77	3.34	2.52	1.99	1.60

# More Choice of Parameters

- “Optimal” choice of  $k_1$  and/or  $k_2$  is possible (for given all-OK ARL and potential shift in mean  $Q$ )
  - For detecting a shift in mean  $Q$  of size  $\mathbf{d}$ , approximately optimal reference values are

$$k_1^{\text{opt}} = \mathbf{m}_Q + \frac{\mathbf{d}}{2} \quad \text{and/or} \quad k_2^{\text{opt}} = \mathbf{m}_Q - \frac{\mathbf{d}}{2}$$

# Example (4.3)

- Process monitoring with
  - $Q = \bar{x}$  based on  $n = 4$
  - all-OK process parameters  $\mathbf{m} = 9.0$  and  $\mathbf{s} = 1.6$   
(so the all-OK distribution of  $Q = \bar{x}$  has  
 $\mathbf{m}_Q = 9.0$  and  $\mathbf{s}_Q = \mathbf{s} / \sqrt{n} = 1.6 / \sqrt{4} = .8$  )
  - *all-OK ARL=370* desired
  - Quickest possible detection of a change of size 2.0 in the process mean (and therefore in mean  $Q$ ) desired
- Set-up of combination high- and low-side scheme?

# Example Continued

- 1st choose the reference values

$$k_1 = 9.0 + \frac{2.0}{2} = 10.0 \text{ and } k_2 = 9.0 - \frac{2.0}{2} = 8.0$$

- Next choose  $h$

$$- K = \frac{k_1 - \mathbf{m}_Q}{\mathbf{s}_Q} = \frac{10.0 - 9.0}{.8} = 1.25$$

– From Table 4.6 (or slide 9),  $H=1.99$

– So take  $h=(1.99)(.8)=1.592$

- Use starting values  $U_0 = 0$  and  $L_0 = 0$

# Predicted Behavior?

- For given  $k_1$  and/or  $k_2$  and  $h$ , with  $U_0 = 0$  and/or  $L_0 = 0$  and normal  $Q$ , it is possible to find (not-all-OK) ARLs (mean times to detection)
  - Use formula (4.15) and
    - Formula (4.16) or (4.17) to find parameters needed to enter Table A.4 for one-sided schemes (one inputs the mean and standard deviation of  $Q$ )
    - Formulas (4.18) and (4.19) to find parameters needed to enter Table A.5 for combined high- and low-side schemes

# Perspective

- Not a tool for plotting “by hand”
- CUSUM and EWMA charts have essentially the same ARLs under small departures from standard conditions, *supposing those departures pertain from time 1 on*
- CUSUM charts do NOT have the have poor “worst case” behavior of EWMA schemes! (one is never “any further from an alarm” than at time 1)

# Possible “Enhancements”

(see Section 4.2.2)

- “Fast Initial Response” CUSUMs

$$U_0 = \frac{h}{2} \text{ and/or } L_0 = \frac{-h}{2}$$

- Shewhart/CUSUM Combinations
  - CUSUM plus a “3.5 sigma” or “4.0 sigma” Shewhart chart “combines the best of both worlds”

# Workshop Exercises

- Find  $k = 1.0$  raw *CUSUMs* for the  $Q$ s below

$i$	$Q_i$	$Q_i - k$	$CUSUM_i$
0			0
1	1		
2	-3		
3	0		
4	1		
5	20		
6	-5		
7	0		
8	1		



# Workshop Exercises

- Find  $k_1 = 1.0$  and  $k_2 = -1.0$  *CUSUMs*

$i$	$Q_i$	$Q_i - k_1$	$U_i$	$Q_i - k_2$	$L_i$
0			0		0
1	1				
2	-3				
3	0				
4	1				
5	20				
6	-5				
7	0				
8	1				

---

# Workshop Exercises

- Suppose  $Q = x$  and process standards are

$$\mathbf{m} = 0 \text{ and } \mathbf{s} = 1$$

If quick detection of a change in process mean of size  $\mathbf{d} = .5$  is of importance, and *all-OK*  $ARL=370$ , set up a combined high- and low-side CUSUM scheme

(what are appropriate  $k_1$ ,  $k_2$  and  $h$  ?)