




Accounts Payable
P Chart for Proportion Defective




Accounts Payable
U Chart for Rate of Defects




Pareto Chart of Accounts Receivable Defects




Cause-and-Effect Diagram Accounts Payable




White Millbase Batch Process
Moving Range Chart




White Millbase Batch Process
Individuals Chart



White Millbase Batch Process
 Moving Range Chart (combined data)




White Millbase Batch Process
 Individuals Chart (combined data)



White Millbase Batch Process (using batch adjustment)

Moving Range Chart



White Millbase Batch Process (using batch adjustment)

Individuals Chart

