


# Cube Plot

## Photolithography Process



Center Points: T=5% D=12% F=1.5%

8.3, 8.6, 8.3, 8.0

$$\bar{Y}_c = 8.30 \quad s^2 = 0.06$$